

Maymead Farms, Inc

09-25-2009

NEW GULLIES FORMING



CHECK DAM



EROSION GULLY



LARGE DENUDED AREA



DENUDED ERODED AREA



DENUDED ERODED AREA



DENUDED ERODED AREA



LARGE ERODED GULLY



SPARSE VEGETATION



DENUDED ERODED AREA



NO OUTLET PROTECTION



SOME NEW GRASS



PROPOSED WASTE POND



ERODED OUTLET PROTECTION



DENUDED ERODED AREA



EROSION GULLY



EROSION & NEW GRASS



LARGE DENUDED AREA



IMPROPERLY INSTALLED CHECK DAM



WATER AROUND CHECK DAM



NEW CHECK DAMS



WASH AROUND CHECK DAM



LARGE DENUDED AREA



EROSION SEDIMENT



FINAL SITE OUTLET



EROSION SEDIMENT



FINAL OUTLET EROSION SEDIMENT



FINAL OUTLET EROSION SEDIMENT



FINAL OUTLET PATH



FINAL OUTLET SEDIMENT



SEDIMENT PAST FINAL OUTLET



SITE EROSION TO STREAM



FINAL CHECK DAM ON SITE



FINAL CHECK DAME ON SITE

